Stream Crossing Data Sheet General Information	Site ID: PLT-P-10
Stream Name: Platte Rives	Road Name: Dymand Rd
Name of Observer(s): Mike S	Date: 3-2-20
GPS Waypoint: GPS Lat/Long: 44.725	79, -86.00945
County: Township:	Range: Sec:
Adjacent Landowner Information:	Additional Comments:
Crossing Information	
Crossing Type: Culvert(s) no.: Bridge Ford Da	m Other:
Structure Shape: Round Square/Rectangle Open Bottom Square	
Inlet Type: Projecting Mitered Headwall Apron	Wingwall 10-30° or 30-70° Trash Rack Other
Outlet Type: Cascade over Riprap Freefall in	ito Pool Freefall onto Riprap Outlet Apron Other
Structure Material: (Metal Concrete Plastic Wood	Multiple Culverts/Spans
Substrate in Structure: None Sand Gravel Rock Mixture	Number the culverts/spans left to right, facing downstream. Include #s in site sketch on back page
General Condition: (New Good Fair Poor	Culvert/ Span # Width (ft) Length (ft) Height (ft) Material
Plugged: % Inlet Outlet In Pipe	
Crushed: % Inlet Outlet In Pipe	
Rusted Through? Yes No Structure Interior: Smooth Corrugated	
	1 4.7 Fb Structure Height (ft): 1 3 A
Structure Water Depth (ft): 1 inlet .8 + or	utlet Perch Height (ft): 1 or NA
Embedded Depth of Structure (ft): inlet 5 + or	utlet8
Structure Water Velocity (ft/sec): 1 inlet or	utlet 95-/20
Structure Water Velocity Measured: At Surface or ft	Below Surface Measured With: Meter or Float Test
Stream Information Stream Flow: None < ½ Bankfull < Bankfull = Bankfull > Bankfull	ull
Scour Pool (if present) Length: Width: Depth:	Upstream Pond (if present) Length: Width:
Riffle Information (measured in a riffle outside of zone of influen	ice of crossing)
Water Depth (ft): 1.3 Bankfull Width (ft): 3 We	tted Width (ft): 3 Water Velocity (ft/sec): 9 ft/s
The state of the s	Clay Bedrock Silt Measured With: Meter or Float Test
Road Information	Tribal Private Other:
Total of the state	
Road Surface: Paved Gravel Sand Native Surface	Condition: Good Fair Poor
	oint: At Stream Other Runoff Path: Roadway Ditch
Embankment: Upstream Fill Depth (ft): 1.5	Slope: Vertical 1:1.5 (1:2) >1:2
Downstream Fill Depth (ft): 1.5	
Left Approach: Length (ft): 25 Slope: 0% 1-5	% 6-10% >10% Ditch Vegetation: None (Partial) Heavy
Right Approach: Length (ft): 200 Slope: 0% (1-5	% 6-10% >10% Ditch Vegetation: None Partial Heavy

¹⁻ Fill out for primary culvert (culvert #1). If multiple culverts are used, number each and use embedded table.

Erosion Information

Use a new row for each distinct gully/erosion location. Note prominent streambank erosion within 50 feet of crossing.

Location of Erosion	Erosio	Erosion Dimensions (ft)		Eroded Material Reaching Stream?		Material Eroded	
Ditch, approach, or streambank Left or right facing downstream	Length Width		Depth			Sand, Silt, Clay, Gravel, Loam, Sandy Loam or Gravelly Loam.	
				Yes	No	(4	
				Yes	No		
				Yes	No		
				Yes	No		
V - W				Yes	No		
If there is erosion occurring, can corrective	e actions, such	h as road d	lrainage me	asures, be	installed to	address the problem? Y N	
Extent of Erosion: Minor Moderate Erosion Notes:	Severe	Stabilize	d				
Photos – enter photo number in blank co							
☐ Site ID	Upstrea	`	-			tream Conditions	
□ Inlet □ Outlet □	☐ Road Ap	proach I	Left	- in	☐ Road A	pproach – Right	
Summary Information							
Would you consider this a priority site?	Fish Passa	age	Erosion	Why?			
						V.	
Would you recommend a future visit to t	his site?	Yes	No W	hy?			
					1.		
Were any non-native invasive species ob	served at the	site?	Yes	No If y	es, what sp	ecies were observed?	
Site Sketch						11.3	ser u e
Draw an overhead sketch of crossing. Be	sure to mark i	North on th	he map and	to indicate	the directi	on of flow. Include major	F A. I.
features documented on form, such as ero	osion sites, mu	ultiple culv	erts, scour	pool, impo	unded wate	er, etc.	Ambie
1	1			11 <		The entre	F Ambre & Barre &
	1 1		1			Josh Birch Birch	BIV IC AL
88	1				N 201	Ala ala	
8			1			Master 131 cen	
					,	WALL CASE	
Sch	- 3				0000		
1	175/8	ā		(35)0-5	145058	V	
- AM OD			3	×1	2	J. J. W. J.	
		12	- E	963	profe.	JUST 1	
The second secon		ad)	5	322	V	A 100 M	
	- 9	\$	25	9.2 B.			
	43	*	2 moint	928	Ø \		
	93	*	5	323	V.		
wooded	48		2	10 May 10 Ma	Se Se	dee	
wooded mostly Enda		*	2	31.2	Se	dge	
wooded anothy Enda	- 68		2	34	Se	dge	

Skinner